

大直高級中學賀眾牌飲水機位置表

111年 7 月 25 日

| 編號 | 安裝位置 | 飲水機序號 | 廠牌 | 型號 | 電壓 | 年份 | 機號 | 濾心規格 | | | | | 濾心更換 | 機台巡檢 | 漏電檢測 | 加熱系統 | 冷卻系統 | 功能操作 | 備註 |
|----|---------------------|-------|-----|-----------------|------|--------|--------|-------|-------|----------|----------|--------|--------|--------|------|------|------|------|------|
| | | | | | | | | UF-61 | UF-64 | UF-65P5 | UF-65CTO | UF-29 | | | | | | | |
| 1 | 教學大樓一棟1樓東側 | 45 | 賀眾牌 | UW-9615AG | 110V | 110/03 | 216860 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 2 | 教學大樓一棟1樓西側 | 18 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278384 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 3 | 教學大樓一棟2樓東側(總務處) | 40 | 賀眾牌 | UW-9615AG | 110V | 109/12 | 203672 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 4 | 教學大樓一棟2樓西側(國中教師辦公室) | 9 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278377 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 5 | 教學大樓一棟3樓東側 | 37 | 賀眾牌 | UW-9615AG | 110V | 108/11 | 152197 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 6 | 教學大樓二棟1樓東側 | 38 | 賀眾牌 | UW-9615AG | 110V | 108/11 | 153836 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 7 | 教學大樓二棟1樓西側 | 17 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278391 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 8 | 教學大樓二棟2樓東側 | 15 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278380 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 9 | 教學大樓二棟3樓西側 | 46 | 賀眾牌 | UW-9615AG | 110V | 110/03 | 216864 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 10 | 教學大樓二棟3樓東側 | 25 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278382 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 11 | 教學大樓二棟2樓西側 | 無 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278381 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 12 | 教學大樓三棟1樓東側(輔導教室) | 23 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278383 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 13 | 教學大樓三棟1樓西側(烹飪教室前) | 26 | 賀眾牌 | UW-31000A-110V | 110V | 103/05 | 762012 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 14 | 教學大樓三棟1樓西側(烹飪教室前) | 10 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278392 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 15 | 教學大樓三棟2樓西側(輔導處) | 41 | 賀眾牌 | UW-9615AG | 110V | 109/12 | 203653 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 16 | 教學大樓三棟3樓東側 | 14 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278366 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 17 | 教學大樓三棟3樓西側 | 39 | 賀眾牌 | UW-9615AG | 110V | 108/11 | 153835 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 18 | 迎曦樓2樓電梯前 | 24 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278393 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 19 | 迎曦樓3樓電梯前 | 11 | 賀眾牌 | UW-30000A-110V | 110V | 101/04 | 781490 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 20 | 迎曦樓4樓電梯前 | 27 | 賀眾牌 | UW-31000A-110V | 110V | 103/05 | 845897 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 21 | 活動中心(側門舞台前) | 21 | 賀眾牌 | UW-30000A-110V6 | 110V | 102/03 | 804886 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 22 | 活動中心(側門舞台前) | 22 | 賀眾牌 | UW-313AS-1-6 | 110V | 101/04 | 762943 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 23 | K書中心2樓 | 12 | 賀眾牌 | UW-9615AG | 110V | 111/03 | 278390 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 24 | 科學館2樓西側(國中音樂教室) | 28 | 賀眾牌 | UW-30000A-110V6 | 110V | 103/09 | 859985 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 25 | 科學館3樓(生物實驗室) | 29 | 賀眾牌 | UW-30000A-110V6 | 110V | 103/09 | 859986 | 1 | 1 | | | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 26 | 教學大樓三棟2樓東側(高導辦前) | | 賀眾牌 | UW-9615AG | 110V | 111/03 | 275916 | | | 1 | 1 | | | ✓ | ✓ | ✓ | ✓ | ✓ | |
| 27 | 教學大樓1棟頂樓(中央水處理系統) | 無 | | 中央水處理系統 | | | | | | UF-47PP5 | UF-47CTO | | | ✓ | / | / | / | ✓ | 借KEY |
| 28 | 教學大樓三棟1樓西側(健康中心) | 無 | | 製冰機 | | | | | | | 1 | | | / | / | / | / | / | |
| 29 | 科學館(實驗教室內) | 無 | 賀眾牌 | UR-5301 | | | | | | UF-501 | UF-502 | UF-513 | UF-504 | UF-505 | | | | | |
| | | | | | | | | | | 10 | 10 | 16 | 16 | 1 | | | | | |

面板霧化,功能正常